


# SA3221H



## Box List

Item No: SA3221H				
Box		Worker	Q C	ganger
Part name	Quantity			
Front wire(前网)	1pcs			
Back wire(后网)	1pcs			
Left wire(左网)	1pcs			
Right wire(右网)	1pcs			
Assembly Instruction(包装图)	1pcs			
Quickset(插条)	4pcs			
Wooden floor(层板)	3pcs			
Grill(密网)	1pcs			
Wooden ladder(梯板)	3pcs			
Wooden screw(木螺母)	12pcs			
pastern cup (13221胶杯)	2pcs			
Top wire(盖网)	1pcs			
Plastic bottom (13221胶盆)	1pcs			
Screw bag(螺丝包)	1pcs			

1. Attach Front、Back、Left、right wire mesh together with 4x attaching clamp.
2. Screw 4x wheels onto bottom of the four legs.
3. Screw Top wire mesh on top of Front wire mesh and Back wire mesh with M6X16 Bolts and M6 Nuts.
4. Use wooden screw tightening will wooden floor at the right position as shown, and will hang wooden ladder on wooden floor of the hole.
5. Slide Grill in space underneath Front wire mesh.
6. Slide Tray in space underneath Grill.
7. Put feeder cups on inside of Body.